




ENVIRONMENTAL RESOURCES AGENCY  
 DEPARTMENT OF ENVIRONMENTAL HEALTH  
 CONSUMER PROTECTION DIVISION  
 1555 Berger Dr. • Suite 300 • San Jose, CA 95112 • (408) 918 - 3400  
 Fax: (408) 258-5891 • Website: www.ehinfo.org

### REPORT OF OBSERVATIONS

DBA / NAME <b>CORDOBA CENTER</b>					DATE <b>8/3/12</b>
ADDRESS LOCATION <b>MONTEREY ROAD</b>					RECHECK DATE
OWNER / OPERATOR					
MAILING ADDRESS					
EMPLOYEE #	SERVICE	PROGRAM / ELEMENT	LOCATION CODE	TIME	WORK AREA



DEPTH	SOIL PROFILE
	(100% Expansion Area)
0 - 6"	clay loam
6" - 1.5"	clay
1.5"	brown sandy clay
3'	less clay
5'	blocky clay less grit
8-9'	loam
10'	more gravel/rock loose w/ sand.
12'	blocky clay
14'	harder digging w/ depth
15'	END (No water/No Rock)

Performed a soil profile in the 100% leachfield expansion area - the results of the soil profile match the previous soil profiles performed in 2006. Therefore, predation tests are not required in the 100% leachfield expansion area.

ANN PEDEN, REAS 408.918.3480	RECEIVED BY
	SPECIALIST <i>Ann Peden</i>
	PAGE 1 OF 1

Attachment: Attachment B - Appeal of Silicon Valley Islamic Center (64492) : Appeals of the Planning Commission decision granting approval of